

# Overview

- Tool Steel Failures
  - Define Tool Steel Properties.
  - Determine Modes of Failures.
  - Identify Probable Failure Causes.
  - Recommend Solutions.

# Important Properties of Tool Steel

NEXT >

- **Harden Ability** – Ability of steel to through harden and form martensite. Proper heat treating is essential. Carbon is a key element in hardening.
- **Wear Resistance** – Resistance to abrasion and erosion. More carbides and higher hardness improve wear resistance. Vanadium, molybdenum, and chromium all contribute to wear resistance.
- **Compressive Strength** - Ability to withstand a constant load without deforming or breaking. Molybdenum contributes to compressive strength

# Important Properties of Tool Steel


NEXT >

- **Toughness** – Ability to absorb impact energy without breaking and chipping. An increased volume of silicone improves toughness. High volumes of large, poorly distributed carbides reduce toughness.
- **Fatigue Strength** – Ability to withstand repeated load cycles without cracking. Large uneven distributed carbides structure and carbides are detrimental, fine carbides, evenly dispersed are highly beneficial.
- **Temper Resistance** - Ability to maintain hardness as surface temperature becomes elevated while having surface treatments applied or while in use. Molybdenum and tungsten contribute to temper resistance.


# Failure Modes of Stamping Dies

NEXT >


Punch & Die	Failure modes	Cause
Forming	Seizure	<ul style="list-style-type: none"> <li>· Increased contact load</li> <li>· Surface softening by deforming heat</li> </ul>
Trimming	Wear · Chipping	<ul style="list-style-type: none"> <li>· Increase applied stress by high strength steel sheet</li> </ul>
Punch	Wear · Breakage	



# Properties Required for Stamping Dies



# Properties Required for Stamping Dies



# Properties Required for Stamping Dies

## Failure Modes

Wear	Abrasion
Galling	Adhesion
Bending	Deformation
Breakage	Large Deep Cracks
Chipping	Edge Cracks
Flaking	Surface De-lamination

## Related Properties


- Carbide Content
- Obtainable Hardness
- Manufacturing Process
- Compressive Strength
- Impact Toughness
- Fatigue Strength
- Temper Resistance

# Properties Required for Stamping Dies

## Failure Modes


Wear	Abrasion
Galling	Adhesion
Bending	Deformation
Breakage	Large Deep Cracks
Chipping	Edge Cracks
Flaking	Surface De-lamination

## Related Properties





# Properties Required for Stamping Dies



# Properties Required for Stamping Dies

## Failure Modes

Wear	Abrasion
Galling	Adhesion
Bending	Deformation
Breakage	Large Deep Cracks
Chipping	Edge Cracks
Flaking	Surface De-lamination

## Related Properties

Carbide Content

Obtainable Hardness

Manufacturing Process

Compressive Strength


Impact Toughness

Fatigue Strength


Temper Resistance

# Toughness Failures

## Face Chipping




## Head Breakage



- Punch failures attributed to lack of tool steel toughness.

# Face Chipping

NEXT >



- Caused by lateral force.
- The Shell Pattern indicates the point of origin.

# Wear


NEXT >



**Wear**

- Caused by tight clearance and punch over entry.
- Wear is the abrasion and erosion of the punch material.

# Galling




**Galling**

- Caused by excessively tight clearance and punch over entry.
- Galling is the welding and part material pick-up on the punch.


# Compressive Failures

## Bending




Load

## Deformation



Load

## Breakage




Load

- Punch failures attributed to high compressive loading typically affect the point area

# Load Breakage

NEXT >



**Point Breakage**

- Caused by excessive compressive load.
- The load is concentrated where the point blends with the shank.



# Perforating Force Formula

NEXT >

$$P = T \times L \times S$$

- **F = Perforating Force**
- **T = Thickness of Part Material**
- **L = Length of Shear (Pi x Dia = Circumference)**
- **S = Shear Strength of Part Material**

## Example

- **T = .180"**
- **L = .281" Diameter (3.14159 x .281 = .882)**
- **S = 78,300**
- **F = .180 x .882 x 78,300**
- **F = 12,442 Lbs.**

# Punch Load Formula

$$P = F / A$$

- **P = Point Load (Psi)**
- **F = Perforating Force**
- **A = Punch Point Area (Pi x Rad<sup>2</sup> = Area)**

## Example

- **F = 12,442**
- **A = .281" Diameter (3.14159 x .140<sup>2</sup> = .0616)**
- **P = 12,442 / .0616**
- **P = 200,626 Psi.**


# Compressive Strength

NEXT >


<b>Tool Steel Grade</b>	<b>Compressive Strength</b>	<b>60% of Strength</b>
<b>S7 (57HRC)</b>	<b>265,000 PSI</b>	<b>159,000 PSI</b>
<b>A2 (60HRC)</b>	<b>305,000 PSI</b>	<b>183,000 PSI</b>
<b>D2 (61HRC)</b>	<b>315,000 PSI</b>	<b>189,000 PSI</b>
<b>DC53 (62HRC)</b>	<b>340,000 PSI</b>	<b>204,000 PSI</b>
<b>M2 (62HRC)</b>	<b>375,000 PSI</b>	<b>225,000 PSI</b>
<b>A11 (63HRC)</b>	<b>400,000 PSI</b>	<b>240,000 PSI</b>

- Commonly used tool steels and their rated compressive strength
- Compressive failures typically start at 60% of the tool steels rated strength

# Grinding Burn




**Heat Check  
Pattern**



- Heat check cracks and burn

# Grinding Damage



- Use mist or flood coolant
- Keep depth of cut at a minimum
- Dress grinding wheel often
- Any discoloration is a sign of grinding stress

# Things to look for:

- **S7** applications with hardness specified HRC 57 or higher. The higher hardness is sought after in an attempt to achieve higher wear resistance and strength however; toughness drops nearly 30% when going from HRC 56 to HRC 58. S7 has relatively low wear resistance, compressive strength, and temper resistance. DC53 has exceptional toughness as well as vastly superior wear resistance, strength, and temper resistance than that of S7.
- **A2** applications – When wear and high load are a concern. Also when applying surface treatments. DC53 has greater wear resistance, strength, and temper resistance to support surface treatments without sacrificing machining and grinding characteristics.
- **D2** application – DC53 almost ALWAYS outperforms D2. DC53 has greater toughness, wear resistance, compressive strength, and temper resistance as well as better machining and grinding characteristics.
- **M2** applications with hardness specified below HRC 60 or when additional toughness is needed. M2 will lose much of its strength and wear resistance when hardened below HRC 60 which presents opportunities. DC53 has superior toughness at equal hardness with nearly the same wear resistance.
- **A11** High vanadium PM (Particle Metallurgy) and **PM M4** applications experience chipping, cracking and or breakage where DC53 even at HRC 62–64 has vastly higher toughness than either grade.

# International Mold Steel

## Any Questions?

**International Mold Steel**

**Florence, KY**

**859-342-6000**

**salesdesk@imsteel.com**

**[www.imsteel.com](http://www.imsteel.com)**

